



de Montageanleitung
en Mounting instructions
fr Instructions de montage
sv Monteringsinstruktion
nl Montage-aanwijzing
it Istruzioni di montaggio
fi Asennusohje
es Instrucciones de montaje
da Monteringsvejledning

Differenzdruckfühler
Differential Pressure Sensors
Sonde de pression différentielle
Differenstryckgivare
Drukverschilopnemer
Sonda di pressione differenziale
Paine-eroanturit
Sondas de diferencia de presión
Trykdifferensføler


QBM2130-1U
QBM2130-30
QBM2130-5



QBM2130-..




DC 8...33 V
DC18...33V
(500 Ω)
4...20 mA



1910z13


Zero Reset

1.




1910z15

2.




1910z14


3.



1910z16




DIP Switch	QBM2030-1U	QBM2030-5	QBM2030-30
	100 Pa	500 Pa	0...3000 Pa
	+/- 100 Pa	250 Pa	0...1500 Pa
	+/- 50 Pa	200 Pa	0...1000 Pa



1916Z06

DIP Switch



For additional information please refer to the following documents on the Internet:



<http://siemens.com/bt/download>

→ search for " QBM2130"